A Case Study: Progressive Collapse Analysis of Existing RC Buildings Using Linear Procedure

Prof. Dr. Mürüde Çelikağ CEng, FICE, Eur Ing, FEANI, AM ASCE

Mürüde Çelikağ and Ahmed Zaid Shams-Al

Eastern Mediterranean University, Famagusta TRNC

14 September 2022

Ref:

Ahmed Zaid Shams-AL, "Progressive Collapse Analysis of Four Existing Reinforced Concrete Buildings Using Linear Procedure", Jan 2012, MSc Thesis, EMU.


























North Cyprus

Progressive Collapse?

Progressive Collapse may happen due to design / construction errors, fire, impact, gas explosion, and terrorist attacks

LOCAL DAMAGE - PARTIAL COLLAPSE:

- When buildings are exposed to unexpected loads, one or more of the load-carrying elements (bearing-walls or columns) may lose their capacity and hence the loads get redistributed.
- Every <u>load redistribution</u> causes the failure of other structural elements, until a new equilibrium state is reached. This may lead to **local damage** or **partial collapse** of a building.

TOTAL COLLAPSE:

- Following partial collapse, if the structure has ductile design, then Alternate Load Paths (ALP) start to transmit the gravity load from the failed elements to the neighboring members until reaching an equilibrium status.
- Otherwise, a **global collapse** for the structure could happen which leads to a serious threat to public safety and property.




















Typology of Progressive Collapse









1. Pancake-type Collapse – earthquake 10 story building – Islamabad, 2005. World Trade Centre Buildings – blast and fire, 2001.

Domino-type Collapse – ice accumulation. Overhead
 Transmission Line Towers–
 Germany, 2005

3. Zipper-type Collapse – wind induced vibration - Tacoma Narrows Bridge– USA, 1940

- **4.** Section-type Collapse when an element of a beam in bending or a bar under axial tension element undergoes a cut, the internal forces from this area are transmitted to the remaining cross-section.
- **5. Instability-type Collapse** occurred due to small imperfections or transverse loading, e.g. the failure of a bracing element can trigger the whole system to collapse.
- 6. Mixed-type Collapse Mixture of the other types of collapse



















Progressive Collapse Examples






Figure 1. World Trade Center Towers [26,29] New York, USA. 2001, terrorist attack by two hijacked commercial airliners hitting the two towers.

















Progressive Collapse Examples



Figure 2. The Windsor Tower, Madrid, Spain [12]. 2005, intensive fire.



Figure 3. Khobar Towers Bombing, Dhahran, Saudi Arabia [11]. **1996**, <u>terrorist attack</u>.

Most of the reported PC events have resulted in large number of casualties besides the enormous loss in the property.



Tower in Boston, United States [10]. **1971**, lack of shoring and low concrete strength.



















Progressive Collapse Examples






Figure 5. Progressive Collapse of the Ronan Point Apartment, London, UK [13,18]. 1968, gas explosion.




Figure 6. Isometric view showing location of blast for Alfred P. Murrah Federal Building [21, 23], Oklahoma, USA. 1995 terrorist attach





















How To Prevent Progressive Collapse

- The designer should increase the structural redundancy.
- What matters <u>is NOT</u> the initial damage to the primary load-bearing elements.
- What matters <u>is</u> the resulting <u>sudden changes to the building's geometry</u> and <u>load-paths</u>.
- Many nations have modified their design codes to include the PC phenomenon.
- In USA, the General Services Administration (GSA 2003) and the Department
 of Defense (DoD UFC 4-23-03) have published specific guidelines for PC
 analysis and designs for the structures.




















Analysis – Design Procedures for Progressive Collapse

PC Analysis Procedures

- 1. Linear Static Procedure (LSP)
 - ✓ Most frequently used: due to being quick, simple, and economic analysis approach
 - ✓ More widely used: to assess the PC potential in low and mid-rise regular structures (≤ 10 floors)
 - ✓ An <u>amplification factor</u> is applied to the load combination to account for the dynamic influence
- 2. Linear Dynamic Procedure (LDP)
- 3. Nonlinear Static Procedure (NSP)
- 4. Nonlinear Dynamic Procedure (NDP)























DoD: "Design of Buildings to Resist Progressive Collapse", 2010

The **DoD Unified Facilities Criteria (UFC 4-23-03)** guideline

- was prepared for the design of the military facilities with three or more stories that necessitate PC considerations.
- b) provides a thorough explanation for PC design and assessment for new and existing buildings constructed by
 - reinforced concrete
 - steel structures
 - masonry
 - wood
 - cold-formed steel structures.



















Objective

DoD - UFC 4-23-03 <u>Alternate Load Path method</u> is based on "sudden column loss". Removal of column from


- middle of the short side
- middle of the long side
- corner of the building

So far it is not clear which one of theses three cases is the most significant and what is the influence of the building height.

Main objective is to assess the PC potential in <u>four existing</u> low to mid-rise RC buildings to investigate

- which column removal case is more critical
- what is the influence of building height.





Methodology

- DoD, UFC 4-023-03 guideline with Alternate Path Method (APM) was used to analyze and re-design the buildings
- 2 four-story and 2 eight-story existing apartment buildings in Famagusta,

| | | | ` ' | \ / | |
|---|---|---|-------|-------|---|
| Northern Cyprus were selected to fulfill the structural regularity required | 1 | 4 | 15.55 | 17.60 | |
| by LIEC guidolino | 2 | 4 | 15.30 | 16.00 | |
| by UFC guideline. | 3 | 8 | 15.20 | 17.80 | |
| Buildings were constructed between the years 1992 and 2004 according to | 4 | 8 | 15.00 | 15.30 | _ |
| Turkish Standards. | | | | | |

- The structural system is a conventional (non-ductile) RC frame.
- <u>3D computer models</u> of each building was prepared, designed and LSP was carried out by using SAP2000 program.
- Analysis results for four buildings were compared. The failed members were identified and re-designed.

















Building

No



Case Study Building Details

Width

x-direction

(m)

No of

Storeys

Length

y-direction

(m)

Dimensions and Reinforcement of the Cross Sections for the Buildings

Building 1 – 4 story

| Castian | Dimonsions (om) | Reinfo | rcement |
|---------|-----------------|--------------|----------|
| Section | Dimensions (cm) | Longitudinal | Stirrups |
| Column | 25X50 | 10φ14 | 10@15cm |
| Column | 35X50 | 12φ14 | 10@15cm |
| Column | 35X75 | 16ф14 | 10@15cm |
| Column | 50X25 | 10φ14 | 10@15cm |
| Column | 60X30 | 12φ14 | 10@15cm |
| Column | 70X30 | 14φ14 | 10@15cm |
| Column | D50 | 10φ16 | 10@12cm |
| Beam | 25X50 | 10φ14 | 10@12cm |

Building 2 – 4 story

| Section | Dimensions (am) | Reinford | cement |
|---------|-----------------|--------------|----------|
| Section | Dimensions (cm) | Longitudinal | Stirrups |
| Column | 25X50 | 10φ14 | 8@12cm |
| Column | 25X60 | 10φ14 | 8@12cm |
| Column | 25X70 | 12φ14 | 8@12cm |
| Column | 30X135 | 24φ14 | 8@12cm |
| Column | 60X25 | 10φ14 | 8@12cm |
| Column | 70X25 | 12ф14 | 8@12cm |
| Beam | 25X50 | 10φ14 | 8@10cm |

Building 3 – 8 story

| Section | Dimensions (em) | Reinfo | rcement |
|---------|-----------------|--------------|----------|
| Section | Dimensions (cm) | Longitudinal | Stirrups |
| Column | 25X70 | 12ф14 | 10@15cm |
| Column | 25X80 | 14ф14 | 10@15cm |
| Column | 25X105 | 16ф14 | 10@15cm |
| Column | 25X110 | 16ф14 | 10@15cm |
| Column | 30X75 | 14ф14 | 10@15cm |
| Column | 30X90 | 16ф14 | 10@15cm |
| Column | 30X105 | 16ф14 | 10@15cm |
| Column | 40X70 | 14ф14 | 10@15cm |
| Column | 80X25 | 14ф14 | 10@15cm |
| Column | 100X25 | 16ф14 | 10@15cm |
| Beam | 25X60 | 10φ14 | 10@12cm |

Building 4 – 8 story

| Section | Dimensions (em) | Reinfor | cement |
|---------|-----------------|--------------|----------|
| Section | Dimensions (cm) | Longitudinal | Stirrups |
| Column | 25X60 | 10φ14 | 8@15cm |
| Column | 25X105 | 14ф14 | 8@15cm |
| Column | 50X25 | 8ф14 | 8@15cm |
| Column | 60X25 | 10φ14 | 8@15cm |
| Column | 60X25 | 10φ14 | 8@15cm |
| Column | 120X25 | 16ф14 | 8@15cm |
| Beam | 25X50 | 10φ14 | 8@12cm |




















Analytical Approach of Study



- Complete the modeling and analysis of each building
- Identify failed members
- Categorize failed members with respect to their actions, floor number, location of the column removal, direction of the notional lateral loads applied to each face of the structure
- Remove 3 columns from each story (first, top and middle)
- 4 story bld. 12 columns removed from all story's
- 8 story bld. 12 columns removed from 1st, 4th, 5th, 8th story's

for deformation-controlled and force-controlled actions

Hence each apartment was analyzed and re-designed for

96 times to cover all required scenarios























Building 1: 4-Storey

Floor Plan Dimensions: 17.6 m x 15.55 m





Building 1 - Deformation-controlled Actions

| 24114118 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 | | | | | | | | | | | | | |
|--|----------|---|-------------|---|-----|--------------|---|-------------|---|---|------------|---|--|
| Floor Number | First St | | First Story | | ory | Second Story | | Third Story | | | Last Story | | |
| Location Direction | C | L | S | С | L | S | С | L | S | С | L | S | |
| North | 5 | 0 | 11 | 4 | 0 | 8 | 2 | 0 | 4 | 0 | 0 | 2 | |
| South | 5 | 0 | 11 | 4 | 0 | 8 | 2 | 0 | 5 | 0 | 0 | 2 | |
| West | 5 | 0 | 13 | 4 | 0 | 8 | 2 | 0 | 4 | 0 | 0 | 2 | |
| East | 5 | 0 | 11 | 4 | 0 | 8 | 2 | 0 | 4 | 0 | 0 | 2 | |
| | | | | | | | | | | | | | |

Max. vertical deflection is at the corner of 4th floor: Building 1= 7.7 mm























Building 2: 4-Storey

Floor Plan Dimensions: 16.0 m x 15.3 m





Building 2 - Deformation-controlled Actions

| Floor Number | First Story | | | Se | cond S | Story | Th | ird Sto | ory | Las | st Story | У |
|--------------------|-------------|---|----|----|--------|-------|----|---------|-----|-----|----------|---|
| Location Direction | С | L | S | С | L | S | С | L | S | С | L | S |
| North | 8 | 7 | 12 | 6 | 2 | 9 | 5 | 1 | 6 | 3 | 0 | 3 |
| South | 8 | 8 | 12 | 6 | 2 | 9 | 4 | 0 | 6 | 2 | 0 | 3 |
| West | 8 | 7 | 12 | 6 | 2 | 9 | 5 | 1 | 6 | 2 | 0 | 4 |
| East | 8 | 7 | 12 | 6 | 2 | 9 | 5 | 0 | 6 | 2 | 0 | 3 |

Max. vertical deflection is at the corner of 4th floor: Building 2= 10.6 mm























Building 3: 8-Storey

Floor Plan Dimensions: 17.8 m x 15.2 m





Building 3 - Deformation-controlled Actions

| building 3 - Deformation-controlled Actions | | | | | | | | | | | | |
|---|-------------|----|----|----|---------|------|-----|--------|----|----|---------|----|
| Floor Number | First Story | | | Fc | ourth S | tory | Fif | th Sto | ry | La | st Stoi | ſy |
| Location Direction | С | L | S | С | L | S | С | L | S | С | L | S |
| North | 12 | 11 | 13 | 11 | 11 | 13 | 10 | 10 | 13 | 9 | 9 | 12 |
| South | 12 | 11 | 13 | 11 | 10 | 13 | 10 | 9 | 13 | 9 | 8 | 12 |
| West | 12 | 12 | 13 | 11 | 11 | 13 | 10 | 9 | 13 | 9 | 9 | 12 |
| East | 12 | 11 | 13 | 11 | 11 | 13 | 10 | 9 | 13 | 9 | 9 | 12 |

Max. vertical deflection is at the middle of 8th floor = 8.8 mm

Max. vertical deflection above the removed column = 3.5 mm




















Building 4: 8-Storey

Floor Plan Dimensions: 15.3 m x 15.0 m



| Floor Number | Fi | First Story | | | Fourth Story | | | Fifth Story | | | Last Story | | |
|-----------------------|----|-------------|----|----|--------------|----|----|-------------|----|----|------------|----|--|
| Location Direction | С | L | S | С | L | S | С | L | S | С | L | S | |
| North | 11 | 20 | 22 | 11 | 14 | 18 | 10 | 14 | 17 | 10 | 10 | 10 | |
| South | 12 | 20 | 23 | 10 | 14 | 17 | 10 | 13 | 15 | 10 | 10 | 10 | |
| West | 11 | 19 | 22 | 10 | 14 | 18 | 10 | 14 | 15 | 11 | 9 | 11 | |
| East | 13 | 22 | 23 | 11 | 17 | 18 | 11 | 15 | 16 | 11 | 10 | 11 | |

Max. vertical deflection is at the middle of 8th floor = 9.7 mm Max. vertical deflection above the removed column = 8.5 mm



5400 mm

15000 mm

3000 mm 42400 mm 3000 mm





3200 mm















Building 1 and 2: 4-Storey

Building 1 - Deformation-controlled Actions

| 24114118 | | | | | | | | | | | | |
|-----------|----|--------|-----|--------------|---|---|-------------|---|---|------------|---|---|
| Floor | Fi | rst St | ory | Second Story | | | Third Story | | | Last Story | | |
| Number | | | | | | | | | | | | |
| Location | С | L | S | С | L | S | С | L | S | С | L | S |
| Direction | | | | | | | | | | | | |
| North | 5 | 0 | 11 | 4 | 0 | 8 | 2 | 0 | 4 | 0 | 0 | 2 |
| South | 5 | 0 | 11 | 4 | 0 | 8 | 2 | 0 | 5 | 0 | 0 | 2 |
| West | 5 | 0 | 13 | 4 | 0 | 8 | 2 | 0 | 4 | 0 | 0 | 2 |
| East | 5 | 0 | 11 | 4 | 0 | 8 | 2 | 0 | 4 | 0 | 0 | 2 |
| | | | | | | | | | | | | |

Building 2 - Deformation-controlled Actions

| Floor Number | Fi | rst St | ory | Se | cond S | Story | Th | ird Sto | ry | Las | st Story | У |
|--------------------|----|--------|-----|----|--------|-------|----|---------|----|-----|----------|---|
| Location Direction | С | L | S | С | L | S | С | L | S | С | L | S |
| North | 8 | 7 | 12 | 6 | 2 | 9 | 5 | 1 | 6 | 3 | 0 | 3 |
| South | 8 | 8 | 12 | 6 | 2 | 9 | 4 | 0 | 6 | 2 | 0 | 3 |
| West | 8 | 7 | 12 | 6 | 2 | 9 | 5 | 1 | 6 | 2 | 0 | 4 |
| East | 8 | 7 | 12 | 6 | 2 | 9 | 5 | 0 | 6 | 2 | 0 | 3 |

Building 1 – 4 story

| | .8 | ••• | | | | | | |
|---------|-----------------|---------------|----------|--|--|--|--|--|
| Section | Dimensions (sm) | Reinforcement | | | | | | |
| Section | Dimensions (cm) | Longitudinal | Stirrups | | | | | |
| Column | 25X50 | 10φ14 | 10@15cm | | | | | |
| Column | 35X50 | 12φ14 | 10@15cm | | | | | |
| Column | 35X75 | 16φ14 | 10@15cm | | | | | |
| Column | 50X25 | 10φ14 | 10@15cm | | | | | |
| Column | 60X30 | 12φ14 | 10@15cm | | | | | |
| Column | 70X30 | 14φ14 | 10@15cm | | | | | |
| Column | D50 | 10φ16 | 10@12cm | | | | | |
| Beam | 25X50 | 10φ14 | 10@12cm | | | | | |

Building 2 – 4 story

| Dunani | 5 - 7 3 6 | | |
|---------|-------------------------|--------------|----------|
| Section | Dimensions (cm) | Reinfo | rcement |
| Section | Dimensions (cm) | Longitudinal | Stirrups |
| Column | 25X50 | 10ф14 | 8@12cm |
| Column | 25X60 | 10ф14 | 8@12cm |
| Column | 25X70 | 12ф14 | 8@12cm |
| Column | 30X135 | 24ф14 | 8@12cm |
| Column | 60X25 | 10ф14 | 8@12cm |
| Column | 70X25 | 12φ14 | 8@12cm |
| Beam | 25X50 | 10φ14 | 8@10cm |
| | | | |

Building 3 and 4: 8-Storey

Building 3 - Deformation-controlled Actions

| Floor Number | | rst Sto | ory | Fo | ourth S | tory | Fif | th Sto | ry | La | st Sto | ſ y |
|--------------------|----|---------|-----|----|---------|------|-----|--------|----|----|--------|------------|
| Location Direction | С | L | S | С | L | S | С | L | S | С | L | S |
| North | 12 | 11 | 13 | 11 | 11 | 13 | 10 | 10 | 13 | 9 | 9 | 12 |
| South | 12 | 11 | 13 | 11 | 10 | 13 | 10 | 9 | 13 | 9 | 8 | 12 |
| West | 12 | 12 | 13 | 11 | 11 | 13 | 10 | 9 | 13 | 9 | 9 | 12 |
| East | 12 | 11 | 13 | 11 | 11 | 13 | 10 | 9 | 13 | 9 | 9 | 12 |

Building 4 - Deformation-controlled Actions

| Floor Number | Fi | rst Sto | ory | Fo | ourth S | tory | Fif | th Sto | ry | La | st Stoi | ſ y |
|-----------------------|----|---------|-----|----|---------|------|-----|--------|----|----|---------|------------|
| Location Direction | С | L | S | С | L | S | С | L | S | С | L | S |
| North | 11 | 20 | 22 | 11 | 14 | 18 | 10 | 14 | 17 | 10 | 10 | 10 |
| South | 12 | 20 | 23 | 10 | 14 | 17 | 10 | 13 | 15 | 10 | 10 | 10 |
| West | 11 | 19 | 22 | 10 | 14 | 18 | 10 | 14 | 15 | 11 | 9 | 11 |
| East | 13 | 22 | 23 | 11 | 17 | 18 | 11 | 15 | 16 | 11 | 10 | 11 |

Building 3 – 8 story

| Section | Di | Reinfo | rcement |
|---------|-----------------|--------------|----------|
| Section | Dimensions (cm) | Longitudinal | Stirrups |
| Column | 25X70 | 12ф14 | 10@15cm |
| Column | 25X80 | 14ф14 | 10@15cm |
| Column | 25X105 | 16ф14 | 10@15cm |
| Column | 25X110 | 16ф14 | 10@15cm |
| Column | 30X75 | 14ф14 | 10@15cm |
| Column | 30X90 | 16ф14 | 10@15cm |
| Column | 30X105 | 16ф14 | 10@15cm |
| Column | 40X70 | 14ф14 | 10@15cm |
| Column | 80X25 | 14ф14 | 10@15cm |
| Column | 100X25 | 16ф14 | 10@15cm |
| Beam | 25X60 | 10ф14 | 10@12cm |

Building 4 – 8 story

| 1 | Section | Dimensions (em) | Reinford | cement |
|----|---------|-----------------|--------------|----------|
| H | Section | Dimensions (cm) | Longitudinal | Stirrups |
| 1 | Column | 25X60 | 10φ14 | 8@15cm |
| H | Column | 25X105 | 14ф14 | 8@15cm |
| 11 | Column | 50X25 | 8ф14 | 8@15cm |
| H | Column | 60X25 | 10φ14 | 8@15cm |
| 1 | Column | 60X25 | 10φ14 | 8@15cm |
| H | Column | 120X25 | 16ф14 | 8@15cm |
| | Beam | 25X50 | 10φ14 | 8@12cm |



















Building 1 and 2: 4-Storey

Building 1 - Force-controlled Actions

| Floor Number | Fi | rst St | ory | Se | cond S | itory | Th | ird Sto | ory | Las | st Story | У |
|--------------------|----|--------|-----|----|--------|-------|----|---------|-----|-----|----------|---|
| Location Direction | С | L | S | С | L | S | С | L | S | С | L | S |
| North | 4 | 0 | 9 | 2 | 0 | 6 | 1 | 0 | 4 | 0 | 0 | 2 |
| South | 4 | 0 | 8 | 2 | 0 | 6 | 1 | 0 | 4 | 0 | 0 | 2 |
| West | 4 | 0 | 9 | 2 | 0 | 6 | 1 | 0 | 4 | 0 | 0 | 2 |
| East | 4 | 0 | 9 | 2 | 0 | 6 | 1 | 0 | 4 | 0 | 0 | 2 |

Building 2 - Force-controlled Actions

| Floor | Fi | rst St | ory | Se | cond S | Story | Th | ird Sto | ry | Las | st Story | y |
|-----------|----|--------|-----|----|--------|-------|----|---------|----|-----|----------|---|
| Number | | - (| |) | | | | | | | | |
| Location | С | L | S | С | L | S | С | L | S | С | L | S |
| Direction | | | | | | | | | | | | |
| North | 6 | 6 | 7 | 3 | 0 | 7 | 4 | 0 | 5 | 0 | 0 | 3 |
| South | 6 | 5 | 10 | 3 | 0 | 3 | 2 | 0 | 3 | 1 | 0 | 1 |
| West | 6 | 5 | 10 | 3 | 0 | 6 | 3 | 0 | 5 | 1 | 0 | 1 |
| East | 6 | 6 | 8 | 3 | 0 | 6 | 3 | 0 | 4 | 1 | 0 | 1 |

Building 1 – 4 story

| Santian | Dimensions (em) | Reinforcement | | | | | | |
|---------|-----------------|---------------|----------|--|--|--|--|--|
| Section | Dimensions (cm) | Longitudinal | Stirrups | | | | | |
| Column | 25X50 | 10φ14 | 10@15cm | | | | | |
| Column | 35X50 | 12φ14 | 10@15cm | | | | | |
| Column | 35X75 | 16φ14 | 10@15cm | | | | | |
| Column | 50X25 | 10φ14 | 10@15cm | | | | | |
| Column | 60X30 | 12φ14 | 10@15cm | | | | | |
| Column | 70X30 | 14φ14 | 10@15cm | | | | | |
| Column | D50 | 10φ16 | 10@12cm | | | | | |
| Ream | 25X50 | 10414 | 10@12cm | | | | | |

Building 2 – 4 story

| | · n - · · · | - | |
|---------|--------------------|--------------|----------|
| Section | Dimensions (cm) | Reinfo | rcement |
| Section | Dimensions (cm) | Longitudinal | Stirrups |
| Column | 25X50 | 10φ14 | 8@12cm |
| Column | 25X60 | 10ф14 | 8@12cm |
| Column | 25X70 | 12φ14 | 8@12cm |
| Column | 30X135 | 24ф14 | 8@12cm |
| Column | 60X25 | 10ф14 | 8@12cm |
| Column | 70X25 | 12ф14 | 8@12cm |
| Beam | 25X50 | 10φ14 | 8@10cm |

Building 3 and 4: 8-Storey

Building 3 - Force-controlled Actions

| Floor Number | Fi | rst Sto | ory | Fo | ourth S | tory | Fif | th Sto | ry | La | ıst Stoı | У |
|--------------------|----|---------|-----|----|---------|------|-----|--------|----|----|----------|---|
| Location Direction | С | L | S | С | L | S | С | L | S | С | L | S |
| North | 1 | 1 | 6 | 0 | 0 | 3 | 0 | 1 | 2 | 0 | 0 | 0 |
| South | 1 | 1 | 6 | 0 | 0 | 3 | 0 | 0 | 2 | 0 | 0 | 0 |
| West | 1 | 1 | 6 | 0 | 1 | 3 | 0 | 0 | 2 | 0 | 0 | 0 |
| East | 1 | 1 | 6 | 0 | 0 | 3 | 0 | 0 | 2 | 0 | 0 | 0 |

Building 4 - Force-controlled Actions

| Floor Number | Fi | rst St | ory | Fo | ourth S | tory | Fif | th Sto | ry | La | ist Sto | ſ y |
|-----------------------|----|--------|-----|----|---------|------|-----|--------|----|----|---------|------------|
| Location Direction | С | L | S | С | L | S | С | L | S | С | L | S |
| North | 1 | 6 | 8 | 0 | 2 | 3 | 0 | 1 | 3 | 0 | 0 | 1 |
| South | 0 | 6 | 8 | 1 | 1 | 4 | 0 | 1 | 3 | 0 | 1 | 1 |
| West | 1 | 5 | 7 | 2 | 2 | 5 | 1 | 2 | 4 | 1 | 1 | 2 |
| East | 1 | 8 | 8 | 1 | 3 | 3 | 1 | 2 | 4 | 1 | 1 | 1 |

Building 3 – 8 story

| Section | Dii () | Reinfo | rcement |
|---------|-----------------|--------------|----------|
| Section | Dimensions (cm) | Longitudinal | Stirrups |
| Column | 25X70 | 12φ14 | 10@15cm |
| Column | 25X80 | 14ф14 | 10@15cm |
| Column | 25X105 | 16ф14 | 10@15cm |
| Column | 25X110 | 16ф14 | 10@15cm |
| Column | 30X75 | 14φ14 | 10@15cm |
| Column | 30X90 | 16ф14 | 10@15cm |
| Column | 30X105 | 16ф14 | 10@15cm |
| Column | 40X70 | 14ф14 | 10@15cm |
| Column | 80X25 | 14ф14 | 10@15cm |
| Column | 100X25 | 16ф14 | 10@15cm |
| Paam | 25V60 | 10+14 | 10@12 |

Building 4 – 8 story

| Section | Dimensions (cm) | Reinforcement | |
|---------|-----------------|---------------|----------|
| | | Longitudinal | Stirrups |
| Column | 25X60 | 10φ14 | 8@15cm |
| Column | 25X105 | 14φ14 | 8@15cm |
| Column | 50X25 | 8ф14 | 8@15cm |
| Column | 60X25 | 10φ14 | 8@15cm |
| Column | 60X25 | 10φ14 | 8@15cm |
| Column | 120X25 | 16ф14 | 8@15cm |
| Beam | 25X50 | 10φ14 | 8@12cm |





















Discussion of Results

- 1. Load increase factor is higher for <u>Deformation-control actions</u> hence more members failed with larger deflection values. Hence the results of DCA are discussed below For all the buildings regardless of the type of actions, the number of stories and the direction of the notional loads, the **column removal from the first floor** located at or **near the middle of the short side** of the facility leads to more damage and relatively greater number of failed members in all floors.
 - This is particularly valid for **Building 1** where the corner column removal causes the second highest member failure in all floors except 4th floor.
 - **REASON:** Span lengths around the removed short side column is relatively large compared to others
 - For Building 2 similar number of members failed due to corner and short side column removal
 REASON: Span lengths around the removed short side and corner column is relatively large compared to long side
 - For Building 3 relatively similar number of members failed in each floor for all column removal scenarios
 REASON: Span lengths around the removed long side and corner column is relatively large and part of the building has smaller overall dimensions



















Discussion of Results

For **Building 4** column removal from the middle of long and short sides caused relatively higher number of member failures when compared to corner column removal, except for the 8th floor, where all column removal scenarios had similar number of member failures.

REASON: Span lengths around the removed long and short side column is relatively larger than the ones around corner column.

- No remarkable difference in the findings when the direction of the notional loads was changed.
- 3. For combination of gravity and lateral notional loads

Max. vertical deflection is at the corner of 4th floor, **Building 1= 7.7 mm**

Building 2= 10.6 mm

Max. vertical deflection is at the middle of 8th floor, Building 3 = 8.8 mm

Building 4 = 9.7 mm

Max. vertical deflection above the removed column, Building 3 = 3.5 mm

Building 4 = 8.5 mm





















Retrofitting of Building 2: 4-Storey and Building 4: 8-Storey

- 1. After completing the analysis of each structure, the failed elements (beams and columns) were identified.
- 2. Consequently, the failed members were re-designed with consideration of retrofitting requirements as per ACI 318R-05 design code and UFC 4-023-03 (DoD, 2010).
- 3. To do this, all the failed components were identified, and then their cross-sections and reinforcement were modified. Iterative analysis and re-design were conducted for each building until all the structural members pass the required checks.





















Building 2: 4-Storey





Building 4: 8-Storey



























Conclusion

It should be emphasized that these findings and recommendations are only to be employed for the regular structures since this study was carried out for regular buildings.

Conclusion 1: Based on the analysis outcomes of this investigation, the removal of column from the middle or near the middle of the **short side** at the first floor of the building is the worst-case scenario which led to more damage and greater number of failed members.

Recommendation: More study needs to be carried out on this to see whether column located at or near the center of short side is the most critical load carry element in the analysis and design procedures. If do using this approach would simplify this type of comprehensive analysis procedure.

Conclusion 2: The results of the analysis illustrate that the higher the building the more failure in the structural members. However, comparing the two eight story buildings there are differences in number of failed members.

Recommendation: More study needs to be carried out on different building heights and plans to arrive at more firm conclusions

Conclusion 3: Observations from the results of this study demonstrated that

- (a) the eight-story apartment buildings are relatively more critical
- (b) the column removed from middle or near the middle of the short side of the building is more significant to **progressive collapse** event when compared to four-story buildings.























Further Recommendations

- 1) Economical analysis of the cost of retrofitting such structures against possible PC should be done.
- 2) Depending on the cost and the risk of buildings for PC, retrofitting can be done at design stage.



















Thank you for your attention





















